75 05 102 18 MAY 1965	SE	CR	iski tema (imissi sukkivetikattyrisis olos). As Bija S Bija M Bija	2 3	Ditech	120	Atel	e wine.
	The Arte 15 day with 40 days economic €	Medical est in the large	"我才会的感觉,你就说一起要的一点的才能的表现的什么解	41	DFA	12	rgeregge av verske skale i stronge et er et en skale et en	v - क्रम्मा अन् (क्रम्मा नक्रमा) ११
; DIRECTOR				5   6	Holes	113	erformissenspromens och sock i grenne fratarisken och effette sock fra formatte sock effette sock fra formatte September 1985 fra formatte sock fra f	arigizacios e enticares un
ж [	25X1A			8	Book and		ntograpia keriman seberah seberahan PER MENUNGKAN SEBERAH BERGERANG SEBERAHAN SEBERAH S BERGERANG SEBERAH SEBERAH SEBERAH SEBERAH	STATE OF THE STATE
Ficht			FASSIPOLES TOUR	PRIORITY				
			<u>.</u>	E PLEASE HE	কারের প্রত্ন প্রত্নার্থকার প্রত্নার ক্রিকার এক প্রত্নার স্থানিকার ক্রিকার স্থান্ত প্রক্রার প্রক্রার স্থানিকার স্থানিকার ও বার ব্যবহার	na orang nagana Para atang Palama Para dang mangana	न्तराहरः । यो स्थेनानां स्वतं अन्यव्यक्षास्य क्ष्याः कृष्यः कृष्यः कृष्यः वस्तु वस्तु वस्तु वस्तु वस्तु वस्तु अञ्चादे अन्यवेश्व स्वतं द्वारा स्वतः प्रश्लाक्षास्य स्वतं प्रश्लाक्षास्य स्वतं स्वतं स्वतं स्वतं स्वतं स्वतं स स्वतंत्राक्षः । त्यान्य स्वतंत्राक्षास्य स्वतंत्राम् स्वतंत्राम् स्वतंत्राम् स्वतंत्राम् स्वतंत्राम् स्वतंत्रा	Total Service of the Control of the
TOR: 0605Z 18 MAY 1965	5						IN: 87693	
ing a series in the second of	omeratio, ehelma aapologa historia	054	1-15		garaganarina yan galigana aniiga salama yagalandi oo ii Malaa siglaya	higgs-coden (codes) (mine	entropie i passe e cipi propies spirali interce e propiesta de la companie de la	Granden (m.)
PRIORITY	25X1A			, ,	CITE		] <sub>Ø379</sub> 2	25>
25X1A REF		· · · · · · · · · · · · · · · · · · ·						
REF								

- 1. LACK OF SUFFICIENT ADVANCE INFORMATION THAT (285C) WAS IN

  70MM FORMAT USING DELTA II (1128) CAMERA CONFIGURATION OCCASIONED

  CERTAIN PROCESSING PROBLEMS:
- A. WE HAD NOT WORKED TYPE 8430 AT 70MM IN OUR PROCESSORS PREVIOUSLY. WE ENCOUNTERED CERTAIN CHEMISTRY PROBLEMS BECAUSE THE ESTABLISHED FORMULAR WERE NOT PROPER AND REQUIRED CONSIDERABLE MODIFICATION.
- B. INDIVIDUAL FRAMES HAD NO DATA CHAMBER OR NUMBERING SEQUENCE WHICH COULD BE ANALYZED HERE. AS A RESULT WE HAD TO ARBITRARILY NUMBER THE DUPE POS IN CHRONOLOGICAL ORDER BEFORE WE COULD EFFECT OUR ROUTE SEARCH. (NOTE: IF EDITING DUE TO HOST OR FRIENDLY COUNTRY COVERAGE WERE SUBSEQUENTLY DETERMINED NECESSARY, RENUMBERING WOULD HAVE BEEN REQUIRED.)
  - C. IT WAS IMPOSSIBLE TO FOLLOW THE TITLING INSTRUCTIONS RESERVED

DΒ

22000

SECRET

25X1A	_	
	0379	(IN87693)

PAGE --2--

BECAUSE OF THE LARGE NUMBER OF CHARACTERS REQUIRED A SINGLE TITLING HEAD ON THE DUAL HEAD BLAKETRON WOULD NOT HOLD ALL CHARACTERS IN 12 POINT TYPE.

- D. TWO OF OUR RECENTLY RECEIVED BLAKETRON TITLERS HAD TO BE DRILLED AND TAPPED TO ACCEPT THE TWO ADDITIONAL 70 MM CONVERTER ROLLERS. THEY HAD COME FROM MANUFACTURER SET UP FOR 9 1/2 INCH ONLY AND HAD ONLY ONE 70MM ROLLER WHICH DID NOT PERMIT ACCURATE TRACKING.
- E. ONE CLEANER WAXER CONSTANTTY PRESENTED TRACKING PROBLEMS
  DUE TO POOR DESIGN CHARACTERISTICS OF 70MM CONVERSION SPINDLE.
- 2. FOR BUDGETARY AND SUPPLY PURPOSES REQUEST WE BE ADVISED IF
  IT IS PLANNED TO UTILIZE THE 70MM FORMAT FREQUENTLY IN FUTURE MISSIONS.
  WILL THE 9 1/2 INCH FORMAT BE PHASED OUT AND IF SO, WHEN? CONTINUED
  USE OF 70MM WILL ALSO HAVE A SIGNIFICANT IMPACT ON OUR PROGRAM TO
  ACQUIRE PHOTO INTERPRETATION READ-OUT EQUIPMENT AND RECTIFICATION
  TRANSFORMATION DEVICES.
- 3. NO TRACKER FILM RECEIVED WITH THIS MISSION. CAN WE ASSUME THAT NORMALLY WE WILL NOT RECEIVE TRACKER?

END OF MESSAGE